

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-15

No. 43

Subject: Incorrect Part Number In Manual

Date: November 18, 1988

Symptom:
(**)

The part number for Q405, Q425, Q427 a 2SA812-M5 type transistor is incorrect in the service manual.

Solution: The correct number is listed below:

Designation	Description	Part Number	
		Former	New
Q405, Q425, Q427	2SA812-M5	8-729-102-75	8-729-100-75

Portable Compact Disc

CSA-13

Reference: FPR 000538

PRINTED IN U.S.A.
CSA-131188-3