

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: RME-7

No. 44R

Subject: Missing Part Number

Date: January 2, 1989

Symptom:
(**)

The part number for the Upper Lid Assembly, battery cover, and plastic overlay are not listed in the service manual.

Solution: Please add the following part numbers to your manual:

| Description | Part Number |
|--------------------|--------------|
| Upper Lid Assembly | 4-922-254-01 |
| Battery Cover | 4-922-048-01 |
| Overlay | 4-922-255-01 |

Miscellaneous

CSA-13

Reference:

PRINTED IN U.S.A.
CSA-131288-3