

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: SS-U520

No. 48

Subject: Incorrect Part Number

Date: November 22, 1988

Symptom:
(**)

The part numbers for the grill frame assembly and the Sony logo are incorrectly listed in the manual.

Solution: Please revise your manual with the following part numbers:

Designation	Description	Former	New
8	Grill Frame Assembly	1-4919-676-1	X-4919-676-1
11	Sony Logo	4-883-602-12	4-883-60 <u>9</u> -12

CSA-13 Speakers

Reference: KCP

PRINTED IN U.S.A.
CSA-131188-8