

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-AV67/650

No. 54

Subject: Part Number Correction -
Main PCB

Date: January 2, 1989

Symptom:
(**)

The part number listed in the service manual for the Main PCB is incorrect. Please note the correct part number as listed below:

Solution:

| Ref. No. | Description | Part Number | |
|----------|------------------|--------------|---------------------------|
| | | Incorrect | Correct |
| 912 | Mounted Main PCB | A-4410-282-A | A-4410- 394 -A |

Receiver
CSA-13

Reference: FPR #J0583

PRINTED IN U.S.A.
CSA-131288-4