

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** STR-AV500/700

**No. 56**

**Subject:** Part Number Clarification -  
IC-701

**Date:** January 2, 1989

**Symptom:**  
(\*\*)

The service manual covers both the STR-AV500 and the STR-AV700. The power output IC (IC-701) is listed only once in the parts list. However, the STR-AV500 and STR-AV700 use two different ICs. Please note the appropriate part numbers as listed below for both models:

**Solution:**

Ref. No.	Description	Part Number
IC-701	STK-4191 V Output IC For STR-AV500	8-749-941-91
	STK-4211 V Output IC For STR-AV700	8-749-920-17

Receiver

CSA-13