

SONY

Hi-Fi Products Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D15

No. 60

Subject: Does Not Play Gold CDV Disc

Date: January 31, 1989



Symptom:
(65)

A gold CDV disc may not be played. These discs have a high RF level.

Solution: Add R554 as shown below:

Designation	Description	Part Number
R554	220k Ohm 1/8W	1-247-887-00

Applicable US Serial Numbers: 214,001 and later



Reference: TNAU88043

PRINTED IN U.S.A.
CSA-13189-2

CSA-13 Portable Compact Disc