

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: AVU-27CD

No. 61

Subject: Missing Adjustment Instructions

Date: February 15, 1989

Symptom:
(**)

The adjustment instructions for the CD player section are missing from the service manual.

Solution: Please refer to the adjustment procedures of the CDP-17F since this unit is very similar.

Compact Disc

CSA-13

Reference:

PRINTED IN U.S.A.
CSV-13189-3