

SONY.

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: PS-LX100/LX285


No. 62

Subject: Reference Numbers Are Interchanged **Date:** February 23, 1989

Symptom:
(**)

Solution: Please correct your service manual as shown below:

Ref. No.	Description	Part Number
19	Head Assembly, PU	4-896-320-01
29	Arm Assembly	X-4895-411-1



CSA-13 Turntable

Reference: KCP

PRINTED IN U.S.A.
CSA-13189-5