

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C20/C30/C40/C50/C50M/C70/C7ESD **No. 78**

Subject: Part Number Missing - Disc Table Frame **Date:** July 25, 1989

Symptom:
(**)


The part number for the Disc Table Frame, shown in the diagram below, is not referenced in the service manual.

Please include this part number in your service manual.

The new frame is missing one of the gear posts. A self-tapping screw with collar must be installed as shown in diagram.

Solution:

Description	Part Number
Disc Table Frame	4-924-407-06
Screw With Collar	4-926-320-01



Reference: T/N AU88050

PRINTED IN U.S.A.
CSA-13789-2

CSA-13 Compact Disc