

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-15

No. 94

Subject: Incorrect Part Number for Screw

Date: November 24, 1989

Symptom:
(**)

The part number for Screw (Ref. No. 24) is incorrectly listed in the service manual.

Solution: Please correct your service manual with the number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
24	Screw B1.7x5 Black	3-318-203-72	3-318-203-71 ₁
	Screw B1.7x5 White	3-318-203-71	3-318-203-72 ₂

Portable Compact Disc
CSA-13

Reference: Part Memo From Tokyo

PRINTED IN U.S.A.
CSA-131189-2