

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-S107

No.101

Subject: Part Number Corrections

Date: February 2, 1990

Symptom:
(**)

Several part numbers are listed incorrectly in the service manual.

Solution: Please correct your service manual with the numbers listed below:

Page	Ref. No.	Description	Part Number
17	104	Limiter Assembly	X-4919-811-1
	105	Plate Assembly, Chuck	X-4919-810-1
17-18	110	Table Assembly, Slide	X-4919-801-1
	177	Chassis (MD) Assembly	X-4919-802-1

Note: Both corrections only apply to the original service manual (Part Number 9-953-197-11), i.e. to all the models with optical block KSS-160C.

Compact Disc
CSA-13