

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** TA-717M/818M

**No.112**

**Subject:** Part Number Correction - IC203

**Date:** February 28, 1990

**Symptom:**  
(\*\*)

The part number listed on page 16 of the service manual for IC-203 (M5F7908) is incorrect.

**Solution:** Please note the correct part number shown below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
IC-203	-8V Regulator IC M5F7908	8-759-604-30	8-759-604-48

CSA-13 Amplifier