

**SONY**

Hi-Fi Products  
Service Bulletin

**Sony Service Company** - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** TCW-R510

**No. 121**

**Subject:** Part Number Correction in the  
Service Manual

**Date:** April 26, 1990

**Symptom:**  
(\*\*\*)

The part number of Q701 on page 17 of the service manual is listed incorrectly.

**Solution:** Please correct the part number on page 39 of the service manual as shown below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
Q701	Transistor	8-729-119-89	8-729-119-78

CSA-13 Tape Deck