

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-110/270/310/470/670/770/950/
970/307ESD

No. 127R2

Subject: Optical Block Connector Now Available

Date: April 19, 1993

This bulletin supersedes Hi-Fi Products Service Bulletin No.127R1


Symptom:
(**)

The connector cord which connects the optical block to the Main Board is now available as a replacement part.

Solution:

Order the cord with connector as shown in the chart below.

DESCRIPTION	PART NUMBER
CORD WITH CONNECTOR	1-690-444-11



CSA-13 CD Player

Reference: FPR-O1168
Autoflagged - NO



PRINTED IN U.S.A.
CSA-13493-5