

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-9

No. 132

Subject: Incorrect Part Number - IC301

Date: October 15, 1990

Symptom:
(**)

The part number for IC301 is incorrectly listed on page 26 of the service manual.

Solution: Please correct your service manual with the part number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
IC301	CXD1161M	8-759-805-43	8-759-805-34

Connect Disc

CSA-13