

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-35

No.138


Subject: Information On New Number For BP-5 Date: October 25, 1990

Symptom:
(**)

There is a new part number for the BP-5 Battery Pack.

Solution: Please add the new part number listed below to your service manual:

Ref. No.	Description	Part Number	
		Former	New
BP-5	Battery Pack	1-528-303-11	1-528-303-41



Reference: GA90009

PRINTED IN U.S.A.
CSA-131090-5

CSA-13 Portable Compact Disc