

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-K444ESII/-K555ES/-K666ES

No. 144R1

Subject: Part Number Change: Record/Playback Head

Date: March 13, 1992

This bulletin supersedes Hi-Fi Products Service Bulletin No.144.


Symptom:
(**)

The part number for the record/playback head has been changed.

Solution:

The part number and wiring diagram for the new record/playback head is shown below:

MODEL	REF. NO.	DESCRIPTION	PART NUMBER	
			INCORRECT	CORRECT
TC-K555ES	534	HEAD, REC/PB (RPA230-3602)	8-825-500-30	1-543-684-11
TC-K666ES	HP101	HEAD, REC/PB (RPA230-3602)	8-825-500-30	1-543-684-11
TC-K444ESII	HRP	HEAD, REC/PB (RPA 230-3602)	8-825-500-31	1-543-684-11



CSA-13 Tape Deck