

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** RM-P700/P700A/P700E

**No.** 145


**Subject:** Replacement Of Upper Lid Assembly **Date:** November 19, 1990

**Symptom:**  
(\*\*)

The hinge on the upper lid assembly has been changed to prevent the lid from disengaging.

**Solution:** Before installing the new upper lid assembly, cut away a portion of the molded shaft in the bottom case assembly, as shown below:

DESCRIPTION	FORMER	NEW
Upper lid assembly	2-381-518-01	2-381-518-02



Miscellaneous

CSA-13

Reference: HF-02290

PRINTED IN U.S.A.  
CSA-131190-4