

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TA-N77ES

No.152

Subject: Availability Of Rubber Foot On
Bottom Of Unit


Date: December 21, 1990

Symptom:
(**)

The rubber foot on the bottom of the unit has no part number in the service manual.

Solution: Please add the following part numbers to your service manual:

Description	Part Number
Ring, Foot Ornamental	4-916-703-01
Foot, Front	4-908-888-01
Foot, Rear	4-908-887-01



CSA-13 Amplifier