

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-GX40ES/GX50ES

No. 155

Subject: Part Number For IC701



Date: December 26, 1990

Symptom:
(**)

The parts list in the service manual for IC701 only lists the part number for STR-GX60ES.

Solution: Please update your service manual with the part numbers listed below:

Ref. No.	Model	Description	Part Number
IC701	STR-GX40ES	STK3042-3	8-749-930-42
IC701	STR-GX50ES	STK3082-3	8-749-921-61



Reference: FPR L2015

PRINTED IN U.S.A.
CSA-131290-4

CSA-13 Receiver