

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** STR-GX40ES

**No.** 173

**Subject:** Incorrect Part Numbers

**Date:** March 19, 1991

**Symptom:**  
(\*\*)

The part numbers listed in the service manual for Q704, Q705, Q754, and Q755 are incorrect.

**Solution:** Please correct your service manual with the part numbers listed below:

Ref. No.	Description		Part Number	
	Incorrect	Correct	Incorrect	Correct
Q704 Q754	2SC2921-OPY	2SC4385-OY	8-729-320-96	8-729-321-30
Q705 Q755	2SA1215-OPY	2SA1670-OY	8-729-320-73	8-729-321-27

CSA-13 Receiver