

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** ST-JX295/JX390

**No. 174**

**Subject:** Tuner Front End Part Numbers


**Date:** March 22, 1991

**Symptom:**  
(\*\*)

Some tuner PC boards use a 7-pin Front End Block. The schematic show only a 10-pin Front End Block.

**Solution:** When ordering a Front End, please be sure to order one which matches the PCB. Part numbers for both Front Ends are listed below:

Ref. No.	Description	Part Number
FE-1	10-Pin Front End Block	1-463-862-21
FE-1	7-Pin Front End Block	1-463-962-11



CSA-13 Receiver