

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** FHB5CD

**No.** 177

**Subject:** Part Number Correction in Service Manual - Power Cord  
**Date:** March 29, 1991

**Symptom:**  
(\*\*)

The power cord part number listed in the service manual is incorrect.

**Solution:** Please correct your service manual with the part number listed below:

Description	Part Number	
	Incorrect	Correct
Power Cord	1-575-706-00	1-575-706- <u>11</u>

CSA-13 Compact Systems