

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technica Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey, 07656

Model: TC-W31

No. 181


Subject: Incorrect Part Number - M901/902 **Date:** March 29, 1991

Symptom:
(**)

The part number listed in the service manual for the Capstan/Reel Motors (M901 and M902) is incorrect.

Solution: Please update your service manual with the correct part number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
M901	Capstan/Reel Motors	X-3335-212-1	X-3358-212-1
M902		X-3335-212-1	



Reference: TC-W31

PRINTED IN U.S.A.
CSA-13391-9