

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company : Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: HCD-H1500

No. 189

Subject: Service Manual Addition

Date: April 19, 1991


Symptom:
(**)

The part number for the eject button is not supplied in the service manual.

Solution: Please update your service manual with the part number information listed below:

Description	Part Number
Eject Button	3-349-055-01

7-2. FRONT PANEL, MAIN BOARD SECTION



Reference: Service Bulletin (Europe) No Number

PRINTED IN U.S.A.
CSA_13491-6

CSA-13 Tuner