

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive - Park Ridge - New Jersey 07656

Model: General

No. 197

Subject: Cleaning Liquid

Date: June 20, 1991

Symptom:
(**)

The recommended cleaning liquid for guides, capstan shafts and magnetic heads, part number 9-919-573-00, is no longer available.

Solution:

Please use either of the following replacement brands:

Product Name	Manufacturer	Catalog Number
Head Cleaner	Chemtronics	C1620L
Professional Cleaner Fluid	Realistic (Radio Shack)	44-1171A

CSA-13 General

Reference:

PRINTED IN U.S.A.
CSA-13691-1