

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive - Park Ridge, New Jersey 07656

Model: CDP-C400/C401/C500

No. 214


Subject: Optical Block Connection Cable Part Numbers

Date: September 20, 1991


Symptom:
(**) The replacement cables were too short.

Solution: Two (2) types of connection cables of correct length and type are now available. Use the part numbers listed below when ordering:

DESCRIPTION	PART NUMBER
BU-5, CNJ101 CABLE	1-690-235-11
BU-5, CNJ103 CABLE	1-690-236-11



1-690-235-11



1-690-236-11

Compact Disc
CSA-13