

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TA-N77ES

No. 215

Subject: C313 And C363 Have Been Changed to Reduce
Power Supply Ripple.

Date: September 25, 1991

Symptom:
(**)

C313 and C363 have been changed to new values in order to reduce the ripple on the constant current power supply.

Solution: The new values for C313 and C363 are listed below:

REF.	FORMER		NEW	
	DESCRIPTION	PART NO.	DESCRIPTION	PART NO.
C313/C363	470 μ F / 100V	1-124-503-00	1000 μ F / 80V	1-126-370-11

CSA-13 Amplifier