

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TA-AX311

No. 217

Subject: Incorrect Part Numbers - Output Transistors
Q712/713/762/763.

Date: September 25, 1991

Symptom:
(**)

The Output Transistors, Q712/713/762/763, are labelled with the incorrect type number on the schematic (page 20) and in the parts list (page 33). The part numbers indicated on page 33 are also incorrect.

Solution: Please make the corrections to the Service Manual as indicated below:

REF. #	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
Q712	2SC-2921-OPY	2SC-3855-QY	8-729-320-96	8-729-320-83
Q762				
Q713	2SA-1215-OY	2SA-1491-OY	8-729-320-73	8-729-320-86
Q763				

CSA-13 Amplifier/Integrated Amplifier