

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-AV500

No. 230

Subject: Unidentified Components Found On Main PCB -
Capacitor and Diode

Date: December 23, 1991


Symptom:
(**)

Several components have been put on the Main board that are not found on the schematic diagram and no change has been made to the Main PCB part number.

Solution:

Please add the following components to your schematic diagram.

REF. NO.	DESCRIPTION	PART NO.
C356	.022 μ F	1-161-055-00
D351	1SS133	8-719-901-33



CSA-13 Receiver