

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: RM-S2070K

No. 250

Subject: No Control Of Main Room CD Player
Functions From Remote Room

Date: March 13, 1992


Symptom:
(25)

Cannot control the CD player/tape functions in the main room from the remote room via the built in repeater/flasher in the RMR-2075 (main room repeater/receiver).

Solution:

The switch setting on the rear of the RMR-2070 (Remote Room Receiver) must be set to the USER STD position in order for the RMR-2070 to perform as a repeater. This is stated on page 7 of the operating instructions manual.

Note: The RMR-2075 will not perform as a repeater if an LED emitter is connected to one or both Control Out jacks on the side panel of the RMR-2075.



Miscellaneous
CSA-13