

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: FH-B5CD, FH-B7CD

No. 258

Subject: Part Number Information: Extension Cable

Date: March 20, 1992


Symptom:
(**)

No availability of extension cable.

Solution:

An extension cable for connection CN202 (main board) to CN101 (BD board) is now available:

DESCRIPTION	PART NUMBER
19-PIN EXTENSION CABLE	J-2501-011-A



19-PIN EXTENSION
CABLE

CSA-13 Component System