

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-180K

No. 270

Subject: Cord (Car Battery) Incorrectly Listed In
The Service Manual.

Date: June 10, 1992

Symptom:
(**)

The cord (car battery) is incorrectly listed in the Service Manual.

Solution:

Please correct your Service Manual as follows:

DESCRIPTION	PART NUMBER	
	INCORRECT	CORRECT
CORD (CAR BATTERY)	DCC-50	DCCE190M

CSA-13 Discman