

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C77ES/C87ES/C715

No. 272


Subject: Part Number Addition: Pulley (R)

Date: June 22, 1992

Symptom: (**)
The part number for the Pulley (R) was omitted from the Service Manual.

Solution: Please add the following part number to your Service Manual:

REF	DESCRIPTION	PART NUMBER
-----	PULLEY (R)	4-934-380-01



CSA-13 CD Player