

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C87ES

No. 273

Subject: Part Number Addition: Transport Lock Screw

Date: June 22, 1992


Symptom:
(**)

The part number for Transport Lock Screw was omitted from the Service Manual.

Solution:

Please add the following information to your Service Manual:

REFERENCE	DESCRIPTION	PART NUMBER
----	SCREW, TRANSPORT LOCK	4-945-435-01



CSA-13 CD Player