

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TA-E1000ESD

No. 282


Subject: Part Number Addition: CP-1001/CP-1002

Date: August 3, 1992

Symptom: (**)
The part number for CP-1001 and CP-1002 was omitted from the Service Manual.

Solution: Please add the following information to your Service Manual:

REFERENCE	DESCRIPTION	PART NUMBER
CP-1001/CP-1002	COMPOSITION CIRCUIT BLOCK	1-232-701-11



Reference: FPR N1403

PRINTED IN U.S.A.
CSA-13792-4

CSA-13 Pre-Amp/Signal Processor