

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C9ESD/C10/C15ESD/C90ES/C100/
C900/C910

No. 300

Subject: Discs Jam When Returned To The XA-10B Magazine

Date: October 30, 1992

Symptom:
(65)


The discs occasionally jam when being returned to the XA-10B magazine.

Solution:

Replace the magazine with an improved version. The improvements were implemented in production starting in August 1991. Improved magazines can be identified as follows:

Improved magazines have a number (1,2,3, or 4) stamped into one of these depressions.

Unimproved magazines do not have numbers stamped into the depressions.



CSA-13 CD Changer