

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: SEQ-411

No. 304

Subject: Power Board PCB Layout Change and Part Number Information: R414 and D411

Date: November 24, 1992


Symptom:
(**)

The power board PCB Layout has been changed and part numbers for R414 and D411 have been added.

Solution: Add the part numbers shown in the chart below to the Service Manual:

REFERENCE	DESCRIPTION	PART NUMBER
R414	68Ω 1/6W	1-249-403-11
D411	DIODE MTZJ33B	8-719-982-26

The PCB layout of the power supply section has been changed. The new mounting diagram is shown below (boards with part number 1-638-580-12 printed on them).



(continued)

Reference: FPR N2407



PRINTED IN U.S.A.
CSA-131192-1

CSA-13 Miscellaneous

