

SONY

Hi-Fi Products Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-211

No. 316


Subject: CD Does Not Play (Focus Not Achieved).

Date: January 15, 1993

Symptom:
(51) The CD does not play. The unit shuts down because focus is not achieved.

Solution: Replace CN-501.

REF	DESCRIPTION	PART NUMBER
CN-501	CONNECTOR, SOCKET 18P	1-695-154-11



Reference: Tech. News GA92047



PRINTED IN U.S.A.
CSA-13193-3

Portable Disc Player
CSA-13