

**SONY**

Hi-Fi Products  
**Service Bulletin**

Sony Service Company · Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** TC-818M, MHC-3300CD

**No.** 321


**Subject:** Clicking Noise

**Date:** February 10, 1993

**Symptom:**  
(64) Clicking noise in either A or B Decks.

**Solution:** Please change the following parts with the improved versions. (same part numbers).

REF	DESCRIPTION	PART NUMBER
203	LEVER (TU ARM REV) ASSY	X-3343-406-1
221	LEVER (TU ARM FWD) ASSY	X-3343-405-1



CSA-13 Tape Deck

Reference: FPR-N2546

PRINTED IN U.S.A.  
CSA-13193-10