

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-33/34/36

No. 325

Subject: Part Number Missing -
Reference No. M901, CLV MOTOR ASSY

Date: March 12, 1993


Symptom:
(**)

The part number for Ref # M901, CLV MOTOR ASSY, which is shown on page 28 of the Service Manual, is not listed in the parts list.

Solution:

Please add the following part number to the Service Manual.

REF	DESCRIPTION	PART NUMBER
M901	CLV MOTOR ASSY	X-2625-460-1



CSA-13 CD Player

Reference:



PRINTED IN U.S.A.
CSA-13293-4