

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C69ES

No. 333

Subject: Part Number Addition: Plastic Window For Front Panel


Date: April 19, 1993

Symptom:
(**)

The front panel (ref. 5) does not include the plastic window which covers the fluorescent display.

Solution: Order the plastic window as follows:

REF	DESCRIPTION	PART NUMBER
-	COVER, INDICATION PLATE	4-952-233-01



CSA-13 CD Player



PRINTED ON RECYCLED PAPER

Reference: FPR-00987
Autoflagged NO

PRINTED IN U.S.A.
CSA-13493-2