

**SONY**

Hi-Fi Products  
**Service Bulletin**

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** CDP-C9ESD/900

**No. 334**

**Subject:** Part Number Correction - Reference No. 112,  
ROLLER (P)


**Date:** April 19, 1993

**Symptom:**

(\*\*) The part number listed on page 26 of the Service Manual for Ref # 112, ROLLER (P), is incorrect.

**Solution:** Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
112	ROLLER (P)	4-927-248-01	4-926-248-01



CSA-13 CD Player



PRINTED ON RECYCLED PAPER

Reference: FPR-Q0985  
Autoflagged - NO

PRINTED IN U.S.A.  
CSA-13493-3