

**SONY**

Hi-Fi Products

**CSA-13**

**Service Bulletin**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** GEN-CD

**No. 356**

**Subject:** New Test Discs Available: TCD-712R  
(Eccentricity) And TCD-731RA (Vertical  
Deviation).

**Date:** October 19, 1993

**Symptom:**

(54) The customer complains of noise or skipping while playing discs.

**Solution:**

The performance of the customer's unit can be confirmed by using the following discs:

DESCRIPTION	PART NUMBER	DISC SPEC.	PRODUCT SPEC.
TCD-712R	J-2501-060-A	140 +/- 5 UM	NO SKIPPING AND NO NOISE WHILE PLAYING TRACKS # 1 AND # 15 FOR 20 SECONDS EACH
TCD-731RA	J-2501-059-A	1.00 +/- 0.05MM	NO SKIPPING AND NO NOISE WHILE PLAYING TRACK # 15 FOR 20 SECONDS. NO PROBLEM WITH DIRECT ACCESS TO TRACK # 15.

Applicable Models: Home CD Players using KSS-150A, KSS-210A, and KSS-240A optical pickup blocks.

All Portable CD Players ("DISCMAN") except D-J50

Reference: Technical News AU-93010  
Autoflagged - NO



PRINTED IN USA  
CSA-131093-2