

SONY.

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: D-802K/12

No. 363

Subject: Part Description Correction - Reference No.
M902, MOTOR ASSY, SLED

Date: November 30, 1993

Symptom:


(**)

The part description for Ref # M902, MOTOR ASSY, SLED, listed on page 30 of the Service Manual is incorrect.

Solution:

Please note the correction as shown below.

REF	DESCRIPTION		PART NUMBER
	INCORRECT	CORRECT	
M902	MOTOR ASSY, SLED	CHASSY ASSY, INCLUDING MOTOR ASSY, SLED	X-2641-537-2



Reference: FPR-O3242
Autoflagged - NO



PRINTED IN USA
CSA-131193-4