

**SONY.**

Hi-Fi Products  
**Service Bulletin**

**CSA-13**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** D-321



**No. 369**

**Subject:** The Prevention Plate Comes Off When Battery Is Inserted backward **Date:** January 11, 1994

**Symptom:**  
(\*\*) The prevention plate comes off when battery is inserted backward

**Solution:** Replace the prevention plate with the following part indicated below.

REF	DESCRIPTION	PART NUMBER
60	PLATE, PREVENTION	4-961-288-02



Reference: Tokyo Fax GA-93014  
Autoflagged - NO



PRINTED IN USA  
CSA-13194-3