

SONY.

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-D159, LBT-D220

No. 371R1

Subject: Loss of tuner preset memory

Date: March 18, 1994

Symptom:
(21)

The tuners preset memory may be lost when the power is turned off after turning the volume up and down several times with the remote commander.

Solution:

Add a 10K resistor to pin 9 of IC601. IC601 is located on the panel board. See diagram below.

