

SONY.

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: GEN-HFP

No. 396

Subject: Availability Of Surround Tester

Date: Mat 27, 1994


Symptom:
(**)

The surround processing circuits of receivers so equipped can be checked by using the Surround Tester available from the National Parts Center.

Solution: The Surround Tester can be ordered as follows:

REF	DESCRIPTION	PART NUMBER
-	SURROUND TESTER	T-9985-569-1

Note: The Surround Tester requires a 9-volt battery to operate. The battery is not supplied with the unit.



Reference:
Autoflagged - NO

PRINTED IN USA