

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-WR445

No. 421

Subject: Mechanical noise in play mode

Date: December 27, 1994

Symptom:

(64)

A loud mechanical noise may be heard while in the play mode. This is due to a lack of oil on the FR gear.

Solution:

Apply a few drops of Sony oil, P/N 7-661-018-18, to the shaft of the FR gear. See diagram below.



