

# Hi-Fi Products Service Bulletin

**CSA-13**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** DTC-57ES/670/750

**No.** 427

**Subject:** Replace T2 guide when replacing Chassis assy

**Date:** January 9, 1995

**Symptom:**

(\*\*)

When a new chassis assembly is installed (P/N X-3366-740-1) the original T2 guide will not fit the opening of the improved chassis.

**Solution:** Assemble and install the new T2 guide using the parts listed below.



